
IMPROVEMENT LOCATION REPORT

EXHIBIT "A"

SITUATE AT 8 ZORRITO COURT, LOT 63, CAMPO CONEJOS PHASE III, COUNTY OF SANTA FE, STATE OF NEW MEXICO

THIS REPORT IS NOT FOR USE BY A PROPERTY OWNER FOR ANY PURPOSE. THIS IS NOT A BOUNDARY SURVEY AND MAY NOT BE SUFFICIENT FOR THE REMOVAL OF THE SURVEY EXCEPTION FROM AN OWNER'S TITLE POLICY, IT MAY OR MAY NOT REVEAL ENCROACHMENTS, OVERLAPS, CONFLICTS IN BOUNDARY LINES, SHORTAGES IN AREA, OR OTHER MATTERS WHICH WOULD BE DISCLOSED BY AN ACCURATE BOUNDARY SURVEY.





LINE TABLE				
LINE	BEARING	LENGTH		
LI	S 71°48'27" W	76.30		
L2	N 79°56'55" E	61,65		

CURVE TABLE				
CURVE	DELTA	RADIUS	LENGTH	
C1	16°11'44"	275.00	77.73	

SOUTHWESTERN TITLE & ESCROW, INC.

FILE No. 110666

	·	
	80 40 0 80 SCALE 1" = 80'	LAND SURVEYING COMPANY, LLC P.O. BOX 4384 505-473-0003 SANTA FE, NEW MEXICO 87505 FAX 471-9050
PROJECT NO. 3781 / ILR		Buyer: Roberto R. Torres & Felicia A. Torres